




The First Assembly
Method:Page 1-3



The Second Assembly
Method:Page 4-6



The Third Assembly
Method:Page 7-9



pin 6x35



①

22 PCS


Dowel 8x30



②

26 PCS

CONNECTOR



③

2 PCS

Cam Cover



④

26 PCS

SCREW 6x12



⑤







16PCS

SCREW 6x26




⑥

8 PCS




1




1

2




3




2

4



5



3

pin 6x35




22 PCS

Dowel 8x30



26 PCS

CONNECTOR



2 PCS

Cam Cover




26 PCS

SCREW 6x12









16PCS


SCREW 6x26



8 PCS




1




4

2




3




5

4





5




6


<p>pin 6x35</p>  <p>①</p> <p>22 PCS</p>	<p>Dowel 8x30</p>  <p>②</p> <p>26 PCS</p>	<p>CONNECTOR</p>  <p>③</p> <p>2 PCS</p>	<p>Cam Cover</p>  <p>④</p> <p>26 PCS</p>	<p>SCREW 6x12</p>  <p>⑤</p> <p>16PCS</p>	<p>SCREW 6x26</p>  <p>⑥</p> <p>8 PCS</p>
--	--	--	---	---	---



2




3




8

4



5



9